



BIKE MODEL - CRADLE Improving Solution



A4050 Set Assemble Status



Current

After Improving

Cradle Improving



Length of Pin

When the A4050 set and Cradle assembled, the contacting area was 1mm since there was original 1mm gap from the HW set already.

After improving the pin length with additional 0.3mm longer, the contacting part from A4050 set and cradle pin gets 1.3mm. It makes stable connection & power supply.

tension

100 gf

150 gf : With strengthen tension, it's improving of any contacting defective during big vibration.

